

# MANOMETER

## INSTRUCTIONS

1. Install the 9 Volt battery in the battery compartment.
2. Push button to power on the meter. (The display will flash +18888, then r 1.03, and finally +0.05 or some #).
3. Zero the meter by pushing the button and hold until + 000 appears, release button. + 0.00 will remain on display.
4. +0.00 means it is zeroed and ready to use.
5. Attach the vacuum line. Readings will be in (Inches of Water)
6. Meter will read 0 to 60 inches of water.
7. The meter will turn-off automatically or you can push the select button and release to turn it off.

Support call 630/920-1300

**Design Technology, Inc**

768 Burr Oak Drive • Westmont, Illinois 60559

**630/920-1300** • FAX 630/920-0011

[www.designtechnology.com](http://www.designtechnology.com) • [www.tinytach.com](http://www.tinytach.com)